## Enclosure 2 – PG&E Data Response 1 (DR1408281), Request date August 28, 2014

We respectfully call your attention to the fact that accident reports and other information or materials that may be submitted as part of a Data Response are provided solely for the confidential use of the Commission and its staff and are not open to public inspection pursuant to Commission Resolution dated February 10, 1970, General Order 66-C and Public Utilities Code sections 315 and 583.

## Related PG&E Ref. No. Metcalf unautho entr

## CPUC Data Request 1 - Raymond Cho Request Date: August 28, 2014

•
Question No. 1:
Log of events and times for this incident. (i.e., alarm
Response to Question No. 1:
Please see attached Metcalf Chronology (Confidential – submitted pursuant to P.U. Code Section 583 and General Order 66-C).
Response provided by: Manager, Security Investigations and Operations, Corporate Security Department, PG&E
Question No. 2:
When did law enforcement respond?
Response to Question No. 2:
Santa Clara County Sheriff's Office was contacted by PG&E at approximately 7:15 a.m. on August 27, 2014, and the first deputies arrived on scene at approximately 7:30 a.m.
Response provided by:  Manager, Security Investigations and Operations, Corporate Security Department, PG&E
Question No. 3:
When did PG&E employees or security personnel realize there was a security breach?
Response to Question No. 3:
Between approximately 6:30 a.m. and 7:15 a.m., a PG&E employee arriving for work at the Metcalf Substation noticed a cut in the east side perimeter fence, reported his observation to his supervisor, and the supervisor reported the cut to a PG&E Corporate Security Department investigator.
Response provided by: Manager, Security Investigations and Operations, Corporate Security Department, PG&E
Data Request Number: DR1408281 Page 1 of 2

Question No. 4:	
A list of the PG&E equipment and property that was removed from N	Metcalf Sub.
Response to Question No. 4:	Attachments Submitted
The following items were removed from Metcalf Substation:	
Items	
Table Threader, (Rigid)	
Smart Bender (Greenlee)	
Portable Bandsaw, (Milwaukee), 5	
Rotary Hammer Drill (Hilti) TE-706	
Rotary Hammer Drill (Hilti) TE-55	
7" Skilsaw (Milwaukee), 2	
Jig Saw (Milwaukee), 3	
Drill, Hole Hawg, (Milwaukee), 2	
Impact Gun, ½" corded (Dewalt)	
Reciprocating Saw, Sawzall (Milwaukee)	
Drill Motor, ½" corded, 4	
Impacts, ½", battery powered, 8	
Demo Hammer (Bosch), 2	
Rotary Hammer Drill, 5/8" (Milwaukee)	
Grinder, 4", 4	
Compressor (Dewalt)	
Plasma Cutter Assembly	
Battery charger, various brands, 5	
Battery, various brands, 10	
Portable Bandsaw (broken)	
Drill motor, 3/8", (broken), 4	
Reciprocating Saw, Sawzall (broken)	
Response provided by: Manager, Security Investigations Security Department, PG&E	and Operations, Corporate
Question No. 5:	
Details about the security system currently in place at Metcalf and de additional security measures that plan to be added.	tailed plans for the
Response to Question No. 5:	Attachments Submitted
•	

Page 2 of 2

Data Request Number: DR1408281