From: USRB

To: Palmer, Leslie L.; SED-Gas Section-North; SED-Gas Section-South; SED-Electric Safety and Reliability Branch -

South; SED-Electric Safety and Reliability Branch - North; SED Wildfire Safety and Enforcement Branch;

compliance@energysafety.ca.gov

Subject: FW: Electric Safety Incident Reported- Southern California Edison Company Incident No: 220905-15265

**Date:** Monday, September 5, 2022 8:20:04 PM

**From:** webmaster@cpuc.ca.gov <webmaster@cpuc.ca.gov>

Sent: Monday, September 5, 2022 8:19:54 PM (UTC-08:00) Pacific Time (US & Canada)

**To:** USRB <usrb@cpuc.ca.gov>

**Cc:** paul.pimentel@sce.com <paul.pimentel@sce.com>

Subject: Electric Safety Incident Reported- Southern California Edison Company Incident No: 220905-

15265

### The Following information regarding this incident has been reported:

**Reporting Date:** 9/5/2022 8:13:48 PM **Incident Date:** 9/5/2022 @ 3:40 p.m.

**Reported By:** Paul C. Pimentel, Principal Manager **Utility Name:** Southern California Edison Company

**Phone Number:** (626)302-5830

Email Address: paul.pimentel@sce.com

Incident Location: Fairview Avenue/Bautista Road Hemet, Riverside County

# **Reasons For Reporting:**

- Fatalities? No (Utility: , Others: )
- Names of Fatalities:
- Injuries? (Utility: , Others: )
- Names of Injured:
- Damage? No (Utility: , Others: )
- Interruption? (Total Customers: , Total Hours: )
- Operator Judgement? Yes
- Media Coverage? Yes

Cause of Incident: Unknown (Other Cause: )

# **Agencies on Scene:**

#### **Facilities Affected:**

- Utilities Facilities: Sprague
- Voltage (KV): 12 kV
- Customer's Facilities:

### **DigIn Information:**

- Excavator Name:
- Contact:
- Phone: ( ) -

# **Incident Recovery:**

- On Scene Date & Time: @ 00:00 a.m.

- Service Restored: @ 00:00 a.m.

**Summary:** Out of an abundance of caution, SCE submits this report as it involves an event that may meet the significant public attention and/or media coverage reporting requirement. The Fairview Fire was reported at 3:37 p.m. in the Hemet area. The cause of the fire is under investigation and has consumed over 500 acres and news reports reflect some structures have been damaged/destroyed. Our information reflects circuit activity occurred close in time to the report time of the fire. The investigation is ongoing.