

Enclosure 2 - Kenneth Bruno Incident Investigation notes from 11-27-18

From: Bruno, Kenneth
Sent: Tuesday, November 27, 2018 12:45 PM
To: Palmer, Leslie L.; Epuna, Matthewson; Lee, Dennis M.
Cc: Nguyen, Ha
Subject: RE: K.Bruno Week ahead 11/26-30, 2018
Attachments: truck over source.jpg

* I was on scene today from 9AM to 10AM. Two SoCal employees stated that SoCal had detected gas involvement on Saturday 11/24/18. The two personnel were [REDACTED] (leak tech [REDACTED]) and [REDACTED] (Field Team Lead)

* The incident was not reported to the CPUC until 11/26/18 - appears to be in violation of our reporting requirements

* I couldn't get any additional info on the injured - we will follow up in a Data request.

* Looks like SoCal Gas suspects a leak from a 2" 1969 Adyl - A main (not yet confirmed because pipe is in the ground).

* SoCal had not yet began excavation because a truck was parked over the suspected leak area and the keys had burned. I directed them to tow the truck and determine the source of the leak

- then have the pipe tested.

* SoCal was still getting gas readings in the ground (leak tech was [REDACTED]). At [REDACTED].

At location #3 they were still reading 15% gas which is the upper explosive limit. I directed them to move the generator/ICE unit further away as it was in close proximity (Approx - 10') to this bar-hole location.

* In addition the neighbor's property was reading 1% gas which is below the lower explosive limit

but still concerning. I asked if the inside was tested and the Supervisor [REDACTED] was

following up with his customer service team.

* SoCal had a ICE unit (thermal oxidizer) and venturi tubes working to vacuum and vent the ground until readings minimized.

* I left around 10AM - Ha Nguyen was anticipated to be on scene at 12PM and will follow up with:

o the repositioning of the ignition source (ICE unit)

o the excavation and removal / preservation of leak source (thought to be 2" main)

o continued "make safe" monitoring to make sure SoCal is protecting neighbors/workers

from gas concentrations still in the nearby soils.

Enclosure 2 - Kenneth Bruno Incident Investigation notes from 11-27-18

- o Standard - incident investigation**
- o Update to PHMSA tonight after HA completes his investigation.**

**Kenneth Bruno
Program Manager
Gas Safety and Reliability Branch
Safety and Enforcement Division
California Public Utilities Commission
Office: 213-576-6297 Cell: 213-220-5569
E-mail: kenneth.bruno@cpuc.ca.gov**
