Enclosure 2



Public Utilities Commission STATE OF CALIFORNIA

Citation Date: October 22, 2013

Citation #: 13-002

Operator ID#: 18484



Richard M. Morrow Vice President Engineering & Operations Staff

Southern California Gas Company 555 W. Fifth Street, GT12B8 Los Angeles, CA 90013-1011

Tel: 213.244.3650 FAX: 213.244.3690

March 2, 2012

Ms. Michelle Cooke Interim Director, CPSD California Public Utilities Commission 505 Van Ness Avenue San Francisco, CA 94102

Dear Ms. Cooke:

This notice is to inform you that during a recent review of our system maps, we discovered that two separate pipe segments had not been leak surveyed in a timely manner. The first segment is 535 feet of two-inch steel gas main in the vicinity of Buffum Street and Barnes Street in the City of Simi Valley, and the second segment is 325 feet of eight-inch plastic main in the vicinity of North Hazard Avenue and Hammel Street in the City of Los Angeles. Upon discovery, we immediately issued and completed the leak surveys. No leaks or hazardous conditions were found on either segment.

In each case, the segments were shown on our system maps, but were not properly identified on our leak survey maps. Not having the segments shown on the leakage maps was likely the result of a clerical documentation error. We conducted a manual review of the piping associated with these segments on our leak survey maps and confirmed that all the pipe is properly identified for future leak surveys. In addition, SoCalGas has recently completed the conversion of these maps and associated mapping systems into a geographical information system (GIS). We plan to use the enhanced capabilities of the new GIS to search for any additional segments that may not have been assigned to a leak survey area. We have initiated work with our information technology department to develop a plan to complete this analysis.

The local authorities for the cities of Los Angeles and Simi Valley and counties of Los Angeles and Ventura are being notified and SoCalGas will provide confirmation of notification as a supplement to this notification.

Please contact me at (213) 244-3650 for any additional questions you may have regarding this notification.

Sincerely

Richard M. Morrow

Vice President

Engineering & Operations Staff